# **Trimble RealWorks**

GEOSPATIAL December 2022

# Version 12.3.2 Release Notes

## Introduction

These release notes describe the features and enhancements that are new in version 12.3.2 of the Trimble<sup>®</sup> RealWorks<sup>®</sup> software. For further information, visit <u>www.trimble.com/support/</u>.

## **System Requirements**

- Operating system: Microsoft<sup>®</sup> Windows<sup>®</sup> 8.1, 10 64 bit
- Processor: minimum 2.8 GHz (Quad-Core) or higher, (additional cores with Hyper-Threading support strongly recommended)
- RAM: minimum 16GB (32GB and higher recommended)
- Graphics card: OpenGL 3.3 compatible with minimum 1GB VRAM (3GB or higher and OpenGL4.4 recommended)
- NVidia graphics cards based on the Ampere architecture (RTX Axxx series) are currently not supported in commands 'Auto-Segment Steel Beams' and 'Auto-Segment Moving Objects'
- 3-button mouse

#### Other requirements

Solid State Drive (SSD) for maximum performance (pref. 500GB) - strongly recommended.

## **Upgrade Procedure**

Install the software from this location (Internet connection required during installation and license or subscription verifications): <u>Support and Downloads</u>

http://geospatial.trimble.com



## **New Features and Enhancements**

## Data Management

Description	New or Enhanced	Feature Overview	Benefit/Comments
Send to <i>Revit<sup>®</sup></i>		The software now creates native Autodesk Revit <sup>®</sup> flanges and valves, giving access to the whole set of Revit <sup>®</sup> tools	Interoperability, productivity

#### **Resolved Issues**

- ZFS import: fixed issue with leveled scans which caused registration inaccuracies
- ZFS import: fixed orientation, scans were rotated by 90° around the vertical axis
- Create Sampled Scans: fixed crash when project was linked to missing TZF scan files
- Send to Revit<sup>®</sup>: fixed crash in Revit<sup>®</sup> plugin when the import options were not filled
- Imaging Ortho-Projection: fixed random endless processing
- Cloud-Based Registration: fixed dropdown issue when merging several groups
- Import and Register: fixed instabilities when some scans are missing in the project

#### http://geospatial.trimble.com

© 2022, Trimble Inc. All rights reserved. Trimble and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.

# **Legal Notices**

Trimble Inc. Geospatial 10368 Westmoor Drive Westminster. Colorado 800021 USA 800-361-1249 (toll free in USA) +1-937-245-5154 Phone +1-937-233-9441 Fax www.trimble.com

## **Copyright and Trademarks**

© 2022, Trimble Inc. All rights reserved. Trimble, and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries.

Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. All other trademarks are the property of their respective owners.

### **Release Notice**

This is the December 2022 release of the Release Notes. It applies to version 12.3.2 of the Trimble<sup>®</sup> RealWorks<sup>®</sup> software.

#### http://geospatial.trimble.com

